


Bub Pendant

DESIGNED IN 2018

ASSEMBLY NOTES | REV 01



GHOSTY WITH THE MOSTY.

Shade and base are one in this deceptively simple and entirely alluring hand blown glass pendant. Part art object and part functional illumination, Bub will spruce up any room.

NEED A HAND?

Contact us at service@bludot.com or **844.425.8368** for assistance.

Parts & Hardware



QTY _____ 2

PT. 1061




QTY _____ 2

PT. 1060




QTY _____ 3

PT. 8021




QTY _____ 1

Mounting Bracket




QTY _____ 2

Rubber Washer




QTY _____ 1

Socket Sleeve



QTY _____ 1

Glass Shade



QTY _____ 1



Pendant

NOTE: Electricity is dangerous. It is recommended to hire a professional electrician to install your lamp.

Step 01

ATTACH MOUNTING BRACKET.

1. Disconnect power.
2. Attach mounting bracket to ceiling electrical box as shown using the provided hardware.




PT. 1060 x 2

Step 02

HARDWIRE PENDANT.

1. Cut pendant cord to desired length, allow 4" above canopy for wiring.
2. Twist matching copper wires together.
 - white to white
 - black to black




PT. 8021 x 2

Step 03

GROUND PENDANT.

1. Locate bare copper wire inside pendant canopy.
2. Twist matching copper wires together in addition to bare canopy wire.
3. If no green wire (ground wire) is present in electrical box, wrap wire around pre-attached screw on mounting bracket and tighten into place.




PT. 8021 x 1

Step 04

ATTACH CANOPY TO BRACKET.

1. Align vertical holes on mounting bracket with side canopy holes.
2. Attach as shown using the provided hardware.




PT. 1061 x 2

Step 05

ATTACH GLASS SHADE.

1. Align pendant and glass shade as shown with rubber washers on each side. A second person is recommended to help with installation.
2. Carefully thread socket sleeve into pendant to hold shade in place. Tighten the socket sleeve with enough pressure to hold the glass shade in place.
Caution: Do not overtighten the sleeve. Overtightening the sleeve can damage the glass shade.
3. Re-connect power.



Additional Information

NOTE

We recommend using a 60W G25 globe bulb.

CLEAN

Clean powder-coated surfaces with a soft cloth or sponge using a mild detergent, such as dish soap, and warm water. Wipe completely dry with a soft cloth. Clean glass surfaces with a high quality cleaner formulated for glass products.

